


Detailed
Damage
Survey
Mapping



Kaua'i: Hurricane Iniki Building Damage Mapped By Parcel

- Red: Demolition with or without Rebuild (1655)
- Orange: Damage or Rebuild (> 50% TMK Value) (266)
- Pink: Roof Damage (< 50% Tax Value) (2332)
- Yellow: Damage, not to Roof (< 50% Tax Value) (492)
- Green: Secondary Structure Demolition with or without Rebuild (269)
- Blue: Secondary Structure Damage or Rebuild (> 50% Tax Value) (90)
- Grey: TMK Boundary
- [#]: Number of parcels

NOTE:
Total number of damaged parcels mapped: 5644
The most severe damage level is shown for each parcel.
Detailed damage maps are plotted for individual areas.

- Wind Field (Fujita, 1994)**
- Red: First Wind
 - Green: Second Wind
 - Blue: Microburst
 - Yellow: Microburst
 - Purple: Microburst
 - Orange: Microburst



Martin & Chock Inc.
Honolulu, Hawaii
www.martinchock.com
N/A/00040W